

FITNESS CERTIFICATE

To be filed by the Inspecting Officer (Asst. Engineer)
(Re: G.O. Ms. 20/70/ PWD Dt. 23 - 01 -1970)

1. Name of the Officer
2. Name of the School
3. Location with name of Education District/ Sub. District
4. Classification of Building as specified in column 4 of the application for fitness certificate and size.

VINOJ T.J.
Bharath vidya mandir
chavakkad/Valapad
Two Permanent three storey
RCC Buildings.

Building - 1 (Three storey RCC Building)

Ground Floor
class Rooms - 6.10x6.10x3.65 - 4 NOS
office Room - 7.60x2.90x3.65 - 1NO
Store Room - 7.60x2.95x3.65 - 1NO
office Room - 7.56x6.10x3.65 - 1NO

First Floor
class Room - 7.67x6.10x3.65 - 1NO
class Room - 7.55x6.10x3.65 - 1NO
Lab Room - 8.22x3.24x3.65 - 1NO
Staff Room - 6.10x3.73x3.65 - 1NO
class Room - 6.32x6.20x3.65 - 1NO
class Room - 5.90x6.20x3.65 - 1NO
class Room - 6.34x6.15x3.65 - 1NO

Second Floor
class Room - 7.70x6.10x3.65 - 1NO
class Room - 7.62x6.10x3.65 - 1NO
class Room - 7.08x6.10x3.65 - 1NO
class Room - 6.20x6.34x3.65 - 1NO
class Rooms - 5.90x6.20x3.65 - 2N
class Room - 6.32x6.20x3.65 - 1NO

5. Period for which the certificate is issued
2025-2026 (upto 31/03/2026)
6. Nature of defects, if any

- a) Foundation and basement
- b) Superstructure
- c) Doors and Windows
- d) Wood work wrought and put up
- e) Roof
- f) Flooring
- g) Miscellaneous (Cracks, etc.)

NIL

Building - 2 (Three storey RCC Building)

Ground Floor
class Rooms - 6.00x6.20x3.80 - 4 NOS
staff Room - 6.00x6.20x3.80 - 1NO
office Room - 3.24x6.10x3.80 - 1NO
class Rooms - 6.35x6.10x3.80 - 5 NOS

First Floor
staff Room - 6.00x6.20x3.70 - 1NO
Lab Room - 9.10x6.20x3.70 - 1NO
class Room - 5.95x6.20x3.70 - 1NO

NIL

6.23x8.20x3.70 - 1N
Reading Room - 6.00x3.22x3.70 - 1N
Library Room - 6.25x6.00x3.70 - 1N
class Rooms - 6.20x6.00x3.70 - 3
class Room - 6.25x6.00x3.70 - 1
Computer Lab - 7.25x(3.25+6.10)/2x3.70 - 1

Second Floor
class Rooms - 6.20x6.00x3.45 - 3
class Room - 6.25x6.00x3.45 - 1
staff Room - 3.00x6.00x3.45 - 1
staff Room - 7.25x(3.25+6.10)/2x3.45 - 1
class Room - 5.90x6.15x3.45 - 1N
class Room - 6.05x6.15x3.45 - 2N
class Room - 6.00x6.15x3.45 - 1N

7. Any major defects noticed which will render the building unsafe in any manner
8. Whether maintenance works have been done properly
9. Whether the structure is sound or not for conducting classes

Yes


The structure is sound for conducting classes under normal wind and weather condition.

Note : 1. The stability of the structure should be examined also with reference to location, altitude, intensity of wind, exposure of flood etc. 2. Any additional observations if deemed necessary for the certificate may be furnished separately with this certificate.

CERTIFICATE

certified that the school building was inspected by me on 23/05/2025 and found to be fit / unfit to conduct classes, for the period 2025-2026 (up to 31/03/2026) for the reasons stated above.

Place: Valapad
Date: 28/05/2025



(Handwritten Signature)

VINOJ T.J.
PEN No: 703278
ASSISTANT ENGINEER
L&SD AND E&M SECTION
VALAPAD GRAMA PANCHAYATH